

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 NR. 28 W.

Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 30 and 31

DESCRIPTION OF CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

WITNESSES TO CORNER 7" Cedar N 20 E 11 Links, marked 1/4 S NBT

7" Tamarack S 79 E 30 1/2 Links, marked 1/4 S NBT

7" Tamarack S 36 W 12 1/2 Links, marked 1/4 S NBT

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was re-established 1/4 corner midway and on line between two Section
corners.

No evidence of original corner.

Corner placed and witnessed on 9 October 1958 with H. S. Peterson, District Forester.

SURVEYORS SEAL

Billy D. Buckler
SIGNED Billy D. Buckler DATE 4-17-59
REGISTERED LAND SURVEYOR