Cons. 4047

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_43_ NR__28 W_

| | | DickinsonCOUNTY |
|-----------------------|-----------------------------|----------------------------|
| DESCRIPTION OF CORNER | 1/4 corner between Sections | |
| DESCRIPTION OF CORNER | MONUMENT1" Pipe with 4" | Brass Cap. |
| WITNESSES TO CORNER . | 13" Cedar S 41 E | 97 Links, marked 1/4 S MBT |
| ••• | 10" H. Maple N 27 E | 71 Links, marked 1/4 S NBT |
| | 9" H. Maple _ 3 78 M | |
| | | |
| | | |

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two Section corners by crew. No eividence of original corner.

Comer was placed and witnessed with H. S. Peterson, District Forester, on 9 October 1958.

SURVEYORS SEAL

SIGNED BILLY D. Buckler DATE 4-29-59
REGISTERED LAND SURVEYOR