## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		Dickinses COUNTY	
		T 43N R 28-29W	
DESCRIPTION OF CORNER _	1/4 cerner between Sections	7 and 12	
CORNER MONUMENT	1" I.D. x 36" irem pipe with	4" aluminum cap	
DATE MONUMENT PLACED AND	WITNESSED January 28, 1969	)	
WITNESSES TO CORNER	Cedar 10 N65°E 37 1ks.	"1/4 S MBT"	
N	Cedar 7 \$56°W 21 1ks.	*1/4 S NBT*	
	Cedar 12 NAA <sup>6</sup> W 29 lks.	*1/4 S NBT*	
	AND		
CIRCLE CORNER REGISTER	ED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Menument placed at site of an eld squared and scribed cedar post which had been re-witnessed about 50 years age (by tree ring count) with a blazed and scribed cedar to the southeast. Too much snow to identify any original BT'S, although there are some down tamaracks and tamarack stumps, some with axe marks, close to the corner. Post is located 2.60 chains Morth of south bank of a small stream (record distance is 2.53 chains) and 118.90 chains South of an original township corner (record distance is 118.75 chains).

The party who set the found scribed post is unknown.

SURVEYOR'S SEAL

10

SIGNED

REGISTERED LAND SERVEYOR

DATE 10/20/69

**DISTRIBUTION:** 

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing