STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		Dickinson	COUNTY
		T43N R _	
DESCRIPTION OF CORNER	Center of Section 6		
CORNER MONUMENT 10 :	L.D. x 36" iron pipe with	1 4" aluminum cap.	
DATE MONUMENT PLACED A	ND WITNESSED October 8	3, 1969	
WITNESSES TO CORNER	B. Spruce 5 163°E	3.6 ft. "1/4S, BT"	
N .	Cedar 11 S40°E	56.2 ft. *1/4S, BT*	
6	Cedar 15 S 2°E	50.5 ft. *1/4S, BT*	
	AND Tamarack 4 M64°W	7.9 ft. *1/4S, BT*	
CIRCLE CORNER REGIST	ERED	•	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner established at intersection of quarter section lines. No evidence that the corner had been established previously.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

REGISTERED LAND SURVEYOR

DATE January 31, 197

Arthur O. Enger

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing