STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

			Dickinson	COUNTY
			T 43 N	
DESCRIPTION OF CORNER	West 1/16	corner between Se	ections 5 and 8	 -
CORNER MONUMENT 4"x4	'x5g' green	cedar pest scribe	ed *W1/16, 5, 8*	
DATE MONUMENT PLACED AND	WITNESSED	September 23,	1969	
WITNESSES TO CORNER	. Cedar 10	N58°E 312 lks.	"1/16S, BT"	
N .	Cedar 9	832°E 33½ 1ks.	*1/16S, BT*	
	AND			
CIRCLE CORNER REGISTER	RED			

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Found a balsam with blases on 4 sides N762°E 13 lks. for an approximate corner. Corner established on line between section corner 20.064 ch. west and 1/4 corner 20.064 ch. east. Found a stream 2 lks wide course SSW which corresponds to a "stream 5 lks. c SW" described in original field notes as being 60.12 ch. west of Sec. Cor. 4, 5, 8, and 9.

SURVEYOR'S SEAL

ر د.

DISTRIBUTION: SIGNED

REGISTERED LAND SURVEYOR

DATE February 1, 1972

Arthur O. Enger

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047 Rev. 10/68