

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 28 W


Dickinson COUNTY

DESCRIPTION OF CORNER South 1/8 between 20-21

CORNER MONUMENT 1" Iron Pipe with 1/4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 12-29-62

WITNESSES TO CORNER..... NBT's: 10" Jack Pine (BT) S 54° W 03 links



9" Jack Pine (BT) N 12° W 40 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies 17 links South of Road.

This corner placed by single proportionate measure between 1/4 Corner to North and Line Tree to South.

No evidence of original corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 8-22-63
REGISTERED LAND SURVEYOR
Billy D. Buckler