

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 28 W


Dickinson COUNTY

DESCRIPTION OF CORNER West 1/8 between 20-29

CORNER MONUMENT 1" Iron pipe with 1/4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 12-29-62

WITNESSES TO CORNER..... BT 1st 5" Cedar (BT) N 54° W 29 1/2 links



10" Cedar (BT) S 10° W 30 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line between Section Corner to West and 1/4 Corner to East.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 8-22-63  
REGISTERED LAND SURVEYOR  
Billy D. Buckler