

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N.R. 28 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 20-29

CORNER MONUMENT 1" Iron Pipe with 1/4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 12-29-62

WITNESSES TO CORNER..... NET'S: 10" Cedar N 42° W 35 1/2 links



10" Cedar S 24° W 23 1/2 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at old Cedar post set by unknown Surveyor. Position checks with other corners in area and with small stream 75 links to East.

FO and several blazes at corner but no evidence of original BT's.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 8-22-63
REGISTERED LAND SURVEYOR
Billy D. Buckler