

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43 N. R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER E. 1/16 Cor. for Secs. 26 and 35.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 4-17-63

WITNESSES TO CORNER..... 7" Cedar (B.T.) N. 49° W., 22 lks.



6" Cedar (B.T.) S. 88° E., 06 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on Line bet. Sec. Cors. to East
and $\frac{1}{4}$ Cor. to West.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 10/17/63
REGISTERED LAND SURVEYOR