

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 43 N.R. 28W


Dickinson COUNTY

DESCRIPTION OF CORNER S 1/16 Corner for Sections 35 and 36.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 4-16-63

WITNESSES TO CORNER..... 9" Cedar (B.T.) N. 77° E., 39 lks.



9" Cedar (B.T.) N. 20° E., 32½ lks.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was placed Midway and on line bet. Secs. Cor. to South and  $\frac{1}{4}$  Cor. to North.

**SURVEYOR'S SEAL**

SIGNED Billy D. Buckles DATE 10/7/63  
REGISTERED LAND SURVEYOR