

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 43 N R 29 W
T 43 N R 30 W

Dickinson

COUNTY

DESCRIPTION OF CORNER Section corner common to sections 18 and 19 T43N R29W and sections 13 and 24, T43N R30W

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER Aspen 6" S 39 E 17 links

Black Cherry 4" S 35 W 23 links


DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed from two original white pine bearing trees, one in fair condition and one in poor condition. Found upper blaze on one, very plain but no scribe marks. Found trace of original stake in ground.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 5 June 1956

SURVEYORS SEAL



Henry S. Peterson

SIGNED _____
REGISTERED LAND SURVEYOR

6/6/56

DATE _____