

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~43-44~~ NR 29 W..

----- Dickinson -----

----- COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 3-4-33-34 -----

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap -----

WITNESSES TO CORNER 8" Cedar N 25° E 15 links -----

"S 3/4 NBT"

10" Cedar S 36° W 17 links -----

"S 4 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner. Found 3 old cedar stakes in place. Found remains of several stump bottoms in proper location.

Found numerous old blazes in vicinity.

Found by Forestry Division Survey Crew.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 11/20/57