

Lenny

**MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION**

JAN 20 1956

LAND CORNER RECORD

T. 43 N NR 30 W

Dickinson

COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 3 and 4

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 10" cedar S 12 E 52 links

11" cedar N 47 W 53 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from original tamarack bearing tree in good condition.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 16 January 1956

SURVEYORS SEAL

Henry S. Petersen
Henry S. Petersen
SIGNED _____
REGISTERED LAND SURVEYOR

DATE 1/19/56