LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in BigLinson	Located In:	Corner Code ≠≠
(County)		
1. Public Land Survey	T 43H R 30H	AI
	т А	
	T R	
2. Property Controlling	s	
in Section	S T R	
2 Miscellaneous	s T R	

Register of Deeds Stamp & File Number

Recorded Plat 4. Lot No. -

5. Private Claims

Property in Sec.

Kay 16, 1994 | Staphan J. Szyszkoski | in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A1) Corner common to Townships 43-448, Ranges 30-31W. Corner praviously recorded by Heal Sperhale in 1963 as restored by proportionate measurement. Corner was monumented by a 1"1.0.x38" iron pipe with aluminum Kimberly-Clark cap and the following MBTs: Balson 5 858M 82 binks, M. Birch 5 830E 84 binks, Black Ash 12 M78E 175 binks, Slack Ash 4 M40M 87 binks. Corner also recorded in 1977 by Thomas P. O'Brien who found Sperhake's monument. Also recorded in 1988 by Kinth Sackett who found the Sperhake monument. (A3) Section corner common to Sections 1-12, T43H-R31H and Sections 6-7 T43H-R30H. Corner previously recorded by Heal Sperhake in 1962 L.2(vol.8)-P.247 as monumented by a 1'x30' iron pipe with aluminum Kimberly-Clark cap and the following MBTs: 8. Ash 11 M33W 37 links, Spruce 7 851W 32 links. Corner subsequently recorded by Thomas P. O'Brism in 1977 as: Found pipe with Kimberly-Clark cap, 12" Twin Seruce \$479 20.8', 12" Maple 8349 24.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A1) Found the 1963 monument slightly disturbed by road construction, leaning southeasterly. Forced monument into unright position so that it was in accord with the two remaining 1963 MBTs: Balsam 5 8568 82 links, now a 5" standing snag, and Black Ash 4 M408 87 links, now 6° in good condition. The other two 1983 MBTs are gone - the birch dead and down, the ash destroyed by read construction. Also checked the 1966 M&Ts as shown below.

(A3) Found and accepted a 1° pipe with K-C cap as described above, in good condition. Remeasured to the 1962 MBTs (The apruce non a 14" stump with measuring notch visible) and marked 3 new MBTs as described below. Did not identify the Maple MBT by O'Brien.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A1) found 1" pipe with aluminum Rimberly-Clark cap. Reseasured to the previously established 1988 NBTs: 7' balson Hatt 26.1' 12' Maple 503W 40.8' 4" Ash \$76E 25.5"

(A3) Found 1" from pipe with aluminum Kieberly Clark cap. 12" B. Ash R31W 23.7' scribing visible 14' Spruce stume \$529 20.8' Blazed and scribed the following new bearing trees: "SG MBT" 10" Spruce #20E 29.4" '87 MBT" 5' Saruca \$47E 28.4' '812 MUT' 12' Balann \$600 45.8' A 4° black ash with champion poster bears MOOF 6.9'

STEPHAN J SZYSZKOSKI LAND SURVEYOR

Surveyor's Michigan License No.

FROM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 20, 1971

MEVISED MAT 14, 1975 REVISED JAN., 1983