

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 44 N.R. 27W


Dickinson COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 16, 17, 20 and 21.

CORNER MONUMENT 1" pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 4-16-63

WITNESSES TO CORNER..... 10" B. Spruce (S. 21 N.3.T.) S. 81° E., 14 lks.



12" B. Spruce (S. 16, N.3.T.) N. 35° E., 64 lks.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced at Wood Post found by Forestry Division  
Survey Crew in 1952. Position checks with other corners in area.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 10/7/63  
REGISTERED LAND SURVEYOR