

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N. R. 27W


Dickinson COUNTY

DESCRIPTION OF CORNER corner common to Sections 19, 20, 29, 30

CORNER MONUMENT 1" pipe with 4" Aluminum cap driven in to ground level.

DATE MONUMENT PLACED AND WITNESSED April 15, 1968

WITNESSES TO CORNER..... Spruce 10" S38W 64 links (DeLaMater)



Spruce 8" N17W 40 links (DeLaMater)

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner was placed from two NBTs in excellent condition. These NBTs were placed by Dean DeLaMater, Registered Land Surveyor. Corner post and monument had been removed.

SURVEYOR'S SEAL

SIGNED H. S. Peterson DATE 4-16-68
REGISTERED LAND SURVEYOR