

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 28. W.

----- Michigan ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 7, 8, 17, 18 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 10" Cedar - N 29 W - 18 Links -----

9" Cedar - S 54 W - 54 Links -----

-----

-----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

**This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Two original B.T.'s in place, in poor condition.**

**Corner was placed and witnessed November 6, 1952.**

SURVEYORS SEAL

SIGNED

*Sean C. [Signature]*  
REGISTERED LAND SURVEYOR

DATE 11/26/52