## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T\_44 NR \_28-29W

				Dickinson _	COUNTY
DESCRIPTION	OF	CORNER	1/4 Section Cor	ner between Sections	1-6
DESCRIPTION	OF	CORNER	MONUMENT 1"	iron pipe with 4" bra	iss cap
WITNESSES	то	CORNER .	14" Red Pine _	N_77° W	58
			18" White Pine	S 32° E	82 links
			·	. <b></b> -	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 Corner from one W. Pine Stp. (probable B.T.) badly burned. Possible trace of stake in soil.

Distance clocked South to Ravine, swampedge, stream. Found old blazes both North and South of here.

Corner placed and witnessed September 24, 1956.

SURVEYORS SEAL

SIGNED SULLAND SURVEYOR DATE 10/18/56