

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 28. W.

D i s k i n s o n COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 18 and 19

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 8" Cedar (1/4s NBT) N 16° E 44 Links

14" Cedar (1/4s NBT) S 16° E 54 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from cedar down, N 23° E 11 Links and

Spruce stump S 44° W 05 Links. Both in poor condition. Two old posts in place with old blazes to east and west. Corner lies in swamp.

Corner was placed and witnessed July 6, 1959 with H. S. Peterson, District Forester.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 4/29/60
REGISTERED LAND SURVEYOR
Billy D. Buckler