

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 NR. 28-29W.

Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 25 and 30

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 6" H. Maple (1/4s NBT) N 20° E 24 Links

5" H. Maple (NBT) S 10° W 05 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced in old fence corner with probable cedar B.T. bearing S 85° W 16 Links. Position fits well with corners north and south on township line.

Corner was placed and witnessed August 17, 1959.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 4/29/60