

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44-43 N N.R. 28 W


Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Sections 1 and 36

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9/23/60

WITNESSES TO CORNER..... 24" W. Pine Stump (NBT) South 109 Links



10" Tamarack (1/4 NBT) N 45° W 280 Links

Corner lies 49 links west of approx. E of gravel road.

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old 1" Iron Pipe. Distances to Section Corners to East and West check good.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler.  
REGISTERED LAND SURVEYOR

DATE

2/20/61

Billy D. Buckler