

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 43-44 N.R. 27-28


Dickinson COUNTY

DESCRIPTION OF CORNER Section Corner for Sections 1, 6, 31, and 36

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9/23/60

WITNESSES TO CORNER..... To Base of 6' Boulder S 60° E 107 links



To Base of 2 1/2' Boulder N 66° E 91 links

North to top of E-W Ridge, North, 115 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two old wood posts. Corner lies in large opening. No trees near. Posts placed by unknown surveyor.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 2/21/61
REGISTERED LAND SURVEYOR

Billy D. Buckler