## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T 44 # NR 29 W

		Dickinso	u COUNI
DESCRIPTION OF CORNER	Section Corn	er common to Sect	ions 8-9-16-17
DESCRIPTION OF CORNER	MONUMENT_	1" pipe with 4"	brass_cap
WITNESSES TO CORNER .	9" Cedar	_ \$ 55° \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	41 links
	7" Cedar	\$ 20° <b>I</b>	36 linke
	9* W. Pine	N 80 II	39_links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner. Found old cedar stake in ground. Numerous old blases N-S-E-W from here. Checked distance south and east to stream.

Section Corner lies in swamp.

Found by H. S. Petersen, District Forester.

SURVEYORS SEAL

SIGNED Silly Suchles DATE 3/11/57