

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 N NR. 29 W ..

..... Dickinson ..... COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 8-9 .....

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap .....

WITNESSES TO CORNER 6" Cedar S 60° E 58 links .....

"1/4S B.T."

6" W. Spruce S 34° W 32 links .....

"1/4S B.T."

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced 1/4 Corner from one Cedar B.T. bearing S 70° E 15 links.

Tree broken off at ground. B.T. in fair condition.

Found post set by Dabey 8/9/50.

1/4 Corner lies in swamp.

Found by H. S. Peterson, District Forester.

SURVEYORS SEAL

SIGNED

*Billy D. Buckles*  
REGISTERED LAND SURVEYOR

DATE 3/11/57