

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44 NR. 29, 30 W

Dickinson

COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 7, 18, 12, 13

DESCRIPTION OF CORNER MONUMENT 1 1/2" Galvanized Iron Pipe with cap

WITNESSES TO CORNER 1 1/4" Red Oak S 12° E 37 links

6" Red Oak N 60° W 61 1/2 links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed Section Corner

Found 1 1/2" Galvanized Iron Pipe with cap in place.

One W. Pine B.T. in place burned badly; Scribe marks visible on bearing blaze.

"No new pipe set"

Corner witnessed September 7, 1956.

SURVEYORS SEAL

SIGNED

*Billy D. Buckles*  
REGISTERED LAND SURVEYOR

DATE 10/15/56