MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_44.45 NR _ 29.11 .

		Dickinson a <u>Marquette</u>	ind COUNTY
DESCRIPTION OF CORNE	R Section Corn	er common to Section	ns_3, 4, 33, 34.
DESCRIPTION OF CORNER	MONUMENT_	l" iron pipe with	ra prese ceb
WITNESSES TO CORNER	9" Cedar	_ <u>n 60° w</u>	ll links
	8ª Cedar	S 21° W	39 links
	9# Cedar	s 76° e	29 links
	,		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Set Section Corner, found two old Cedar Posts in place.

No evidence of original witnesses.

Checks with 1/4 Corner 1/2 mile South and Swamp Edge, 4.00 chains North; Checks with 1/4 Corners, 1/2 mile East and West.

Corner placed and witnessed September 21, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 10/18/56-