

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 29 W. .

----- Dickinson ----- COUNTY

DESCRIPTION OF CORNER .. 1/4 Section Corner between Sections 16 and 17 ..

DESCRIPTION OF CORNER MONUMENT .. 1" pipe with 4" brass cap.

WITNESSES TO CORNER .. 10" Cedar .. N 53° W .. 21 links ..

----- 13" Cedar .. S 24° E .. 31 links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replace Corner from one Cedar B.T. in poor condition.

1/4 Corner found while working with H. S. Peterson, District Forester,
in this vicinity.

Corner placed and witnessed December 6, 1955.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 2/14/56
REGISTERED LAND SURVEYOR