

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 29 W. . .

. . . Dickinson . . . COUNTY

DESCRIPTION OF CORNER . . . 1/4 Section Corner between Sections 16 and 17 . . .

DESCRIPTION OF CORNER MONUMENT . . . 1" pipe with 4" brass cap. . . . .

WITNESSES TO CORNER . . . 10" Cedar . . . N 53° W . . . 21 links . . . . .

. . . 13" Cedar . . . S 24° E . . . 31 links . . . . .

. . . . .

. . . . .

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replace Corner from one Cedar B.T. in poor condition.

1/4 Corner found while working with H. S. Peterson, District Forester, in this vicinity.

Corner placed and witnessed December 6, 1955.

SURVEYORS SEAL

SIGNED Billy D. Buckles . . . . . DATE 2/14/56  
REGISTERED LAND SURVEYOR