

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 44 N. R. 29-30W


Dickinson COUNTY

DESCRIPTION OF CORNER South 1/16 Cor. bet. Secs. 25 and 30.

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap.

DATE MONUMENT PLACED AND WITNESSED 2-12-63

WITNESSES TO CORNER..... 8" Aspen (B.T.) N. 22° E., 06 Lks.



8" Cedar (B.T.) S. 23° W. 42 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on line bet. Sec. Cor. to South and  $\frac{1}{2}$  Cor. to North.

SURVEYOR'S SEAL

SIGNED Billy D. Buckles DATE 10/7/63  
REGISTERED LAND SURVEYOR