

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 44. NR. 29. W.

Dickinson COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 25 and 26

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 6" H. Maple (1/4s NBT) N 49° E 44 Links

8" H. Maple (1/4s NBT) S 75° W 209 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced at old fence corner. No evidence of original B.T.'s. Found evidence of several burned cedars at Corner. Corner lies West of road, 70 Links.

Corner was placed and witnessed August 17, 1959.

SURVEYORS SEAL

SIGNED

*Billy D. Buckler*  
REGISTERED LAND SURVEYOR  
Billy D. Buckler

DATE 4/29/60