MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T.44 NR 29 W

					_ ້ກີສ	- G R F I) ā O D _		COUN	, ,
DESCRIPTION	OF	CORNER	Section .	on_corn	er_com	ion to Si	ections_25	5 <u>.</u> 26. 1	35,_36.	
DESCRIPTION	OF	CORNER	MONUI	MENT_	l"_Pipe	with 4'	Brass Cal)		
WITNESSES	то	CORNER	26" W.	Pine S	mado" -	(ĥbī) _	<u>s 66° e</u>	_ 6Q L	inks	
			13" W.	Pine_S	twmp_	(NBT) _	_N_50 ⁰ _W_	_32 <u>L</u> :	inks	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was replaced from two W. Pine stumps bearing N 40° E

36 Links and S 15° W 33 Links. Position fits hill and line tree to north and

Corners East and West.

Corner was placed and witnessed August 17, 1959

SURVEYORS SEAL

SIGNED SILLY DATE 4/29/60

REGISTERED LAND SURVEYOR

Billy D. Buckler