STATE OF MICHIGAN DEPARTMENT 0F **NATURAL RESOURCES**

LAND CORNER RECORD

		Dickinson	COUNTY
		т	
DESCRIPTION OF CORNER	Section Corner 22, 23, 26, an	nd 27	
CORNER MONUMENT	1" I.D. x 36" iron pipe with	4" aluminum cap	
DATE MONUMENT PLACED AND	D WITNESSED _ May 12, 1969		
	. White Spruce 10 S4 E 49	links "826 NBT"	
N	White Spruce 6 N50°E 28	links "S23 NBT"	
23	White Spruce 7 N63°W 17	links "S22 NBT"	
	AND		
CIRCLE CORNER REGISTE	RED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument set from a probable original cedar BT to the southwest. Found a down and burned cedar corresponding in size to the recorded original, with an apparent partially grown-over face and definite overgrowth on a piece of bark. The location checks almost exactly with stream crossings to the north and west as recorded in the original field notes, and with swamp edges to north and west. Swamp edges to the east and south are indefinite and inconclusive. General area of corner was located from proportionate measurements to known corners in four directions from this one.

Variation at this corner is 0015 West.

SURVEYOR'S SEAL

SIGNED

Cothur O. Engre DATE 2/26/70
REGISTERED LAND SUBJEYOR

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing