## SURVEY & REMONUMENTATION

MAR 0 3 1998

## LAND CORNER RECORDATION CERTIFICATE

RECORDED

*****	Manufacture and	- 2		74	841-1		4070
-!lina	Requirement	ΟI	ACT	74.	MICH.	P.A.	797U
				,			

INDIAN OF IT

For cor	ners in SECTION				13.	/ <b>/</b> U	こし	W	) Ar	1 0	U ;	ŧ	
Dick	inson (County) La Twp.	Located In:	Corner Code ##										
Sago.	la Twp.					REG	187	T.R	or D	EED	)Ş		
1. Put	olic Land Survey	T R T R T R T R	I-5 & G-7		·R	DIC DIC	KIN ayri	901 901	i coi	JAT Ji Zi	Y >ደብ፤ -	í	
in S	Section S	T R		•	_ • •								
-		TR	K	egiste	r or i	Jeec	18 5	tam	ip &	riie	Nun	1ber	
4. Lot	No , Reco	rded Plat				_	_					.,	
				_ , [	N B	<u>с</u>	<u>,                                    </u>	E F	F G	<del></del> -	l J	K	<del>''</del>
				2	6		5	-		- ફ્રે —	<u></u> }	:-}	-1-
				3		┽—	-	$\vdash$		╬	╀┤	$\dashv$	
	_	<b></b>		4	<u> </u>	<del>- -</del> -	8	<b>-</b> -	·	-10-		ı—	-12-
			mber 6 , 19 97 ,	5		4				4-4	•	-	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the					1_ 1 <sub>.</sub> 8	4_1	<b>/</b>	-16	5——	-15—	1.	<b>-</b>	-13-
current manual of survey instructions of the United States Department of the Interior, Bureau of Land				7		<u> </u>		$\sqcup$	_	$\perp$	$\sqcup$	_	
Manager	nent or by a decree of a Cou	irt of Law and/or that the corn	er points mentioned in lines 3, 4 and 5	8	[ 19	2	0		1——	_  _22	-2;	3	_  24
			of Land Surveyors or by a Decree of a	9						L		$\perp$	
	r Law; established, re-es: ed below:	tabusned, monumented, re-	monumented, recovered, found as	10	30_			21		-27	2		
•	-	ere all in the came town s	ind range, may be recorded	11	Ĭ.			LĨ	$\perp$	Ĺ	آلـــا		Ĭ.
11012.	on this certificate.	, s, an in the seme town a	ma range, may be recorded	12		Τ,			.				26
	on this portingate.		\ !	13	31- 	Ţ~,	<u>-</u>	]			آ	7	
A. Des	cription of original mon	ument and accessories an	nd/or subsequent restoration:	.0.									
I-5		to Sections 10	1										
_	Post set by J	. Burt, D.S. in	SEptember 1848.										
	Tamarack 16	S79W 41 lks.											
	Dept. of Cons	ervation pipe &	cap set by Dean DeLa	Mate	r	n	10	-9	-51	•			
	Spruce 8 S30	W 16 1ks. Sp:	ruce 8 N15W 18 1ks.										
G-7		to Sections 15											
			September 1848.		_								
	Tamarack 10	N66W 228 lks.	Tamarack 8 S44E 2	28 <b>1</b>	ks.	, , ,-,	-	,	- 1				
	Dept. of Cons	ervation pipe &	cap set by H.S. Pete	rson	or	1 7	- 1	0-	20.				
			amarack 4 S 05E 9 applied in restoring or reestablishin	g corn	er:								
I-5	Found Dept. of	f Conservation p	pipe & cap.										

Spruce NBT rotted-off at base.

Found Dept. of Conservation pipe & cap. G-7Both NBT's blown-over and dead.

Tamarack NBT alive.

ACCEPTED BY THE DICKINSON COUNTY SURVEY PEER GROUP AS THE CAPIC AL CORNER UNDER MICHES A PUBLIC OT 345 OF 1990 AT A MILLIE A FLED IN

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Dept. of Conservation pipe & cap.

Dbl. Cedar 10 N74E 19.85 feet Cedar 5 N32W 16.32 feet. Cedar 6 S69W 25.30 feet. Cedar 11 S67E 11.15 feet.

N45W 3.0 feet. Carsonite Marker

Dept. of Conservation pipe & cap. Tamarack 6 S 05E 6.00 feet. Tamarack 5 **S60E** 17.95 Tamarack 4 18.70 feet. N86E 12.65 Tamarack 5 864W

B. Spruce 5 N11W 18.60 feet.

S45W 3.0 feet. Carsonite Marker

All bearings are magnetic.

OF MI 4. **EDWARD** KAZIANKA LAND **JRVEYOR** No. EREO LAND

Signed by Siever Rage

\_\_ Date \_Dec. 10, 1997

Surveyor's Michigan License No. 14765

FORM APPROVED BY MICHIBAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1871

REVISED MAY 14, 1975 REVISED JAN., 1983

Liber 2 Page 310