

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

DICKINSON COUNTY

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. <u>44</u> N. <u>E.</u> R. <u>30</u> W.	<u>C5, C4, C3</u>
2. PROPERTY CONTROLLING IN SECTION	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. _____ S. _____ R. _____ E. _____ W. _____	_____
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on July 8, 1980, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

- Corner C5:** Original monument and accessories not found. Found 1-1/2" iron pipe and square cedar post. Fits good with other corners.
- Corner C4:** Original monument and accessories not found. Found 1-1/2" iron pipe and square scribed cedar post. Fits good with other corners.
- C3:** Original monument and accessories not found. Found 1-1/2" iron pipe and very old square post.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- Corner C5:** Reestablished at 1-1/2" iron pipe.
- Corner C4:** Reestablished at 1-1/2" iron pipe.
- Corner C3:** Reestablished at 1-1/2" iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- Corner C5:** 1-1/2" iron pipe.
11" Sugar S71°W 18.7 ft., S18, NBT
12" Sugar S28°E 25.9 ft., S17, NBT
- Corner C4:** 1-1/2" iron pipe.
6" Sugar S71°W 20.6 ft., 1/4S, NBT
8" Sugar N71°E 19.2 ft., 1/4S, NBT
- Corner C3:** 1-1/2" iron pipe.
5" Spruce S85°E 28.5 ft., S8, NBT
4" Tamarack N29°E 76.9 ft., S5, NBT
4" Tamarack S38°W 46.0 ft., S7, NBT

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY Keith L. Sackett DATE 9-5-82

APPROVED AND SIGNED BY Keith L. Sackett DATE _____

MICHIGAN REGISTERED LAND SURVEYOR
Keith L. Sackett
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006

