SURVEY & REMONUMENTATION

APR 27 1995

94 OCT 26 AM 8: 56

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich PA 1970

| For corners in | i mig itequit | omone of Aot 1 1, mon can. | LINDA M. TWITCHELL REGISTER OF DEEDS |
|--|--|--|---|
| EATON (County) | Located In: | Corner Code ## | CĂTON COUNT Y. MICH. |
| HAMLIN TOWNSHIE 1. Public Land Survey 2. Property Controlling in Section 3. Miscellaneous | T 1N R 3W T R R T R T R T R S T R S T R S T R | B-4 | LIBER 3 PAGE AGY |
| Property in Sec. | S T R, | | Register of Deeds Stamp & File Number |
| I, David Clifford, do hereby certify that under requirement manual of survey instructions above were in conformance with Court of Law; established, reexpressed below: | in a field survey on | 7 23 , 19.94 If 1970, the corner points mentioned rules therefore as required in the ment of the Interior, Bureau of Land points mentioned in lines 3, 4 and 5 Land Surveyors or by a Decree of a onumented, recovered, found as | 6 18 17 16 15 14 13 13 14 15 16 17 18 18 18 18 18 18 18 18 18 18 18 18 18 |
| on this certificate. | ,,, | | 12 31 32 33 34 35 36 |
| | onument and accessories and et in GLO surveys. | | 1 |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Searched at apparent location of corner and found 1 Bar 3' North of centerline Steele Hwy. on Fence line to North with all of R. Lester's witnesses still standing. Excavated 6'x4'x 3' deep hole and found plowpoint in a ring of stones next to $\frac{1}{2}$ "bar. Although no record exists of the establishment of this corner as a plowpoint it is obvious that this was done at some time in the past. As the Plowpoint is very close to the intersection of the 4 lines this Surveyor accepted it as corner and replaced 1" bar with Standard Bar & Cap. Measured North 2658.06 to B-3, South 2655.59 to B-5, East 2646.88 to C-4, West 2607.65 to A-4 where

2. No record of corner being set by County Surveyor.3. R. Keller LS# 20707 reported finding a plow point in a survey

dated Oct. 1979 recorded in Liber 3 of Surveys page 53

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Standard 3/4" Bar and PA 345 Cap PS 25837 next to plowpoint

N.E. Cor. Brick House NAZ 180° 101.531

Found Nail & Tag # 20707 in W. Side Power Pole NAZ 174° 24.22' Found Nail & Tag # 18998 in W. Side 12" Hick. NAZ 19° 24.04' Found Nail & Tag in S.E. side 36" Oak NAZ 58° 51.57'

THE OF MICH DAVID L CLIFFORD LAND SURVEYOR 25837 q_{F_D} TALL ON A L

Date July 26, 1994

25837 Surveyor's Michigan License No. __

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

- 3. (Continued) Keller set capped iron alongside plowpoint. South R.R. Tie 26.15' S5°E Tele. Pole 24.2' N60°E 24" Oak 23.96' N5°E 12" Hick. 51.6'
- 4. A. Williams LS# 21275 reported using Corner in a Survey dated Mar. 1983 and recorded in Liber 3 of Surveys page 310. Nail & Tag in 12" Hick. N20°E 29.0' Nail & Tag in 30" Oak N65°E 51.6' Nail & Tag in 10" Box Elder S10°W 30.65'
- 5. R. Lester LS# 18998 recorded corner in Liber 3 of Corners page 62 in Mar. 1988 as a Found Bar & Cap as described in Survey recorded in Liber 3 of Surveys page 53.

 N.E. Cor. Brick House South 101.5'

 Found Nail & Tag in East side 12" Shagbark N.E. 24.0'

 Found Nail & Tag in South Side 36" Oak N.E. 51.5'

 Found Nail & Tag in West Side Tele. Pole South 24.2'

 R. Lester also used this corner in a survey dated Mar. 1988

 Recorded in Liber 4 of Surveys page 418.
- 6. R. Helsel used corner in a survey dated Sep. 1992 recorded in Liber 5 of surveys page 576 with the same mon. and witness as in item 5. Helsel's PS # is 18994