FILED copy

FEB 2 2 1996 LAND CORNER RECORDATION CERTIFICATE COMMISSIO Filing Requirement of Act 74, Mich. P.A. 1970

94 NOV 30 AM 9: 11

-or	corners	in	

	EATON ICOUNTY ARMED TOWNSHIP	Located in:	Corner Code ## (A-1) Br	LINDA M. TWITCHELL REGISTER OF DEEDS EATON COUNTY, MICH.
1 1	Public Land Survey	т <u>2N</u> я <u>5W</u>	M-13	FATOR COUNTY, MICH.
	, , , , , , , , , , , , , , , , , , , ,	T R	· · · · · · · · · · · · · · · · · · ·	
		T R		
		T R	, <u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>	1 10003 P. 533
<u>)</u> .	Property Controlling	S T R		LIBER 3 Pg 330
	in Section	S T R		
3.	Miscellaneous	S		Register of Deeds Stamp & File Number
	Property in Sec.	S R		

__ , Recorded Plat . 1. Lot No. 5. Private Claims ___

Dave Clifford , in a field survey on October 15 10 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land vianagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
 - 1. Original Post set by John Mullet D.S. in Nov. 1824 Beech 16 S83E 15 Do 7 S82½W 22
 - 2. Marginal note in the Eaton County Road Commission (ECRC) copy of the GLO notes by Morrell Newcombe, County Surveyor (No date)
 Sugar N.Wly 42.5'
 Rock N.Ely 33.5' Fence corner S.Ely 34.50' Fence corner S.Wly 34.50'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Searched at apparent location of corner and found 3/4" pipe in monument box by using witnesses in items A4, A5, and A6. Excavated bottom of box and found stone on S.E. side of pipe. Accepted stone and pipe as perpetuation of corner and set 3/4" X 24" smooth steel bar in top of pipe. Corner lies on extended centerlines of Cochran Columbia.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Standard 3/4" X 24" Bar & PA 345 Cap PS 25837 in Monument Box

Set Nail & Tag # 25837 in E. Side 38" Maple NAZ 343° 118.40' Found MDOT Tag in S. Side 36" Maple NAZ 67° 56.68'
"L" Shaped Gate Bolt in E. Side R.R. Tie Fencepost NAZ 326° 31.50'
N.W. Corner House Foundation NAZ 144° 118.75' Boat Spike (POT US-27) NAZ 280° 11.78'

Signad by	Dave (lillard
Surveyor's	Michigan License No	25837
04,70,0,0		

November 22, 1994 Date

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. REVISED MAY 14.

3. Corner called stone and crockery in a survey by M.H. Bailey, County Surveyor, in Book 2 page 23 in August 1868.

4. Arden Pierson LS 13039 witnessed corner for the Michigan Department Of State Highways (MDSH) in March 1968 on MDSH Form 280 as a found 3/4" pipe in Monument box.

26" Maple N65°E 56.73' 25" Maple N15°W 119.45' N.W. Corner House S25°E 118.72

5. Bob Carr LS 20704 recorded corner in Liber 2 of Corners page 88 in Feb. 1974 as a found monument box.

30" Maple N70°E 56.66": Utility Pole S60°E 62.43' N.W. Corner House S20°E 118.71

6. Larry Bryan LS 25832 recorded corner in Liber 3 of corners page 25 in Apr. 1987 as a found 1" iron pipe in monument box.

MDOT Nail & Tag in E. Side 38" Maple N20°W 119.38' MDOT Nail & Tag in S. Side 36" Maple N70°E 56.70' N.W. Corner House Foundation S50°E 118.77'