NOV 0 2 1993

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE 93 OCT 27 PM 2: 38

Fo	r corners in	Filing Require	ement of Act 74, Mich. P	
	EATON (County) BROOKFIELD TOWNSHIP	Located In:	Corner Code ##	LINDA M. TWITCHELL REGISTER OF DEEDS EATON COUNTY, MICH.
1.	Public Land Survey	T <u>1N</u> R <u>4W</u> T R T R T R	A7	LIBER 3 PAGE 326
	in Section S	T R		,
3.		T R		Register of Deeds Stamp & File Number
	Lot No, Recor			A B C D E F G H I J K L

OCTOBER 7 \_ , 19 **\_93** do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

- A. Description of original monument and accessories and/or subsequent restoration:
- 1. POST SET BY SYLVESTER SIBLEY, DEPUTY SURVEYOR IN 1825 WITNESSED BY: BEECH 8" NORTH 51 EAST 21 LINKS, BEECH 16" SOUTH 61 EÁST 40 LINKS, AND (POST M-7 WALTON TOWNSHIP) NORTH 58 LINKS.(38.28')
- 2. NO RECORD OF SUBSEQUENT SURVEYS FOUND IN COUNTY SURVEYORS RECORDS.
- 3. PRIVATE SURVEYORS RECORDS REVEAL NO ADDITIONAL DATA.
- 4. EATON CO. ROAD COMM. PLANS (1917) SHOW CORNER TO BE 58 LKS. SOUTH OF M-7 AND 5' NORTH OF C/L MAHAN ROAD.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-7

NO PHYCIAL EVIDENCE EXISTS AS TO LOCATION OF A-7. SET CORNER AT RECORDED DISTANCE OF 58 LINKS (38.28') SOUTH OF M-7 WALTON TOWNSHIP, AND ON LINE BETWEEN M-7 AND M-8 WALTON TOWNSHIP. EXCAVATED THRU 6" OF BIT. CONCRETE AND 30" OF GRAVEL TO ORIGINAL GROUND (CLAY). FOUND NO EVIDENCE OF ORIGINAL NO TOPSOIL WAS ENCOUNTERED DURING THIS EXCAVATION. IT IS PRESUMED CORNER. THAT ANY EVIDENCE WAS REMOVED DURING PREVIOUS ROAD CONSTRUCTION.

SET STANDARD 3/4" X 24" BAR IN MONUMENT BOX ON CENTERLINE OF COCHRAN ROAD AND FIVE FEET NORTH C/L MAHAN ROAD.

C. Description of monument for corner and accessories established to perpetuale locating the position of the corner:

SET STANDARD 3/4" X 24" EATON COUNTY REMONUMENTATION BAR AND PA 345 CAP #30090 53.40 FOUND NAIL AND TAG #11370, S/S POWER POLE, 53 A 7. . Az. 215 SET GALV. NAIL AND TAG #30090, SE/S 24" OAK 42.22' SET GALV. NAIL AND TAG #30090, SW/S 18" OAK 26.60' Az. 300 SET GALV. NAIL AND TAG #30090, SW/S FENCE POST 322 49.45 Az. PIPE 38.28' IN MON BOX (M-7 WALTON) 0 Az.

Signed by \_//\_

\_\_ Date \_\_\_\_OCTOBER\_13\_\_1993

Surveyor's Michigan License No. \_30090

ENDS APPROVED BY MICHIGAN STATE ROARD OF LAND SURVEYORS, JAN. 28, 1975 **REVISED MAY 14, 1975** 

TE OF MICHIGA

DAVID R.

LOHR

PROFESSIONAL

SURVEYOR

No.30090

OFESSIONA