DEC 1 6 1996

COMMISSION

on this certificate.

## EATON COUNTY REMONUMENTATION

Copy

96 OCT 28 AM 9: 21

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

| For Corners in   |  |                          | 1                            | LINDA M. TWITCHELL<br>REGISTER OF DEEDS<br>EATON COUNTY, MICH. |
|--|--|--------------------------|------------------------------|--|
| (County)   | Located In:  | Corner Code              | 9 <i>≠</i> ≠                 | EATON COUNTY. MICH.  |
| WEST PACORNER SECTION 30 ON RANGE LINE KALAMO TOWNSHIP 2. Property Controlling in Section 3. Miscellaneous   | T R F F F F F F F F F F F F F F F F F F                  |                          | Re                           | Liber 3, Pg. 1716  Tegister of Deeds Stamp & File Number       |
| Property in Sec. S   | · / /  |                          |                              |  |
| 4. Lot No, Reco  |  |                          |                              | - ABCDEFGHIJKL   |
| 5. Private Claims  |  |                          |                              | - ,  |
|  |  |                          |                              |  |
| •  |  |                          |                              |  |
| RICHARD W. STEADMAN  |  | OCTOBER 9                | 96                           | 12-  |
| t,, in do hereby certify that under require  | a field survey on  | A of 1970 the corner     | _ , 19 ,<br>points mentioned | 5  |
| in lines 1 and 2 above were in cor   | nformance with regulations                               | and rules therefore a    | s required in the            | 6 18 17 16 15 15 14 13   |
| current manual of survey instructio  | ns of the United States Dep                              | partment of the interior | r, Bureau of Land            | · 7  |
| Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a |  |                          | 8 19 20 21 22 23 24          |  |
| above were in conformance with the<br>Court of Law; established, re-es<br>expressed below:   | a rules of the Michigan Boar<br>tablished, monumented, r | e-monumented, reco       | vered, found as              | 10 30 29 28 27 26 25   |
| NOTE: Not more than 4 corne  | ers, all in the same town                                | and range, may be        | recorded                     | 11   |

- Description of original monument and accessories and/or subsequent restoration:
- 1. THIS CORNER WAS NOT SET BY THE GENERAL LAND OFFICE.
- 2. COUNTY SURVEYOR OSCAR G. CHURCH, 9-26-1876, (VOL. 2, P. 37) "SET STONE FOR POST" NO WITNESSES GIVEN.
- 3. CORRESPONDING STANDARD CORNER WAS RECORDED BY DOUGLAS W. BONNEMA, PS # 12579, BARRY COUNTY LCRC #462, RECORDED SEPT. 14, 1992, "SET CAPPED REROD ON C/L GRAVEL TO N & S...."
- Description of corner evidence found and/or method applied in restoring or reestablishing corner:

CORNER LOCATION FALLS IN A DEEP ROAD CUT. ALL PREVIOUS MONUMENTATION CAN BE PRESUMED DESTROYED. FOUND IRON FOR STANDARD CORNER AS RECORDED BY BONNEMA. OCCUPATION LINE EAST FROM A-10 HAS BEEN OBLITERATED. TRAVERSED 2 1/2 MILES OF RANGE LINE FROM A-13 TO A-8, TYING IN OCCUPATION LINES FROM SURVEY BY CHURCH. ACCEPTED POSITION OF STANDARD CORNER BY BONNEMA N-S; HOWEVER, DETERMINED CORNER SHOULD BE PLACED ON RANGE LINE DEFINED BY M-9 AND M-11, T2N R7W. PLACED REMON IRON AT MID POINT ON RANGE LINE BETWEEN RESTORED A-9 AND RESTORED A-11, IN VERY CLOSE CONFORMANCE WITH PROPORTIONAL DISTANCES TO OCCUPATION LINES REMAINING FROM THE SURVEY BY CHURCH. FIELD WORK SUPERVISED BY BRIAN REYNOLDS, PS #31602.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET STANDARD EATON COUNTY REMONUMENTATION MONUMENT (3/4" X 24" SOLID IRON WITH PLASTIC CAP INSCRIBED "PA 345 PS 11370") FOUND NAIL IN THE S. SIDE OF 6" WALNUT N58°W 28.79" SET 20d NAIL W/REMON TAG IN THE EAST SIDE OF A 12" CHERRY S33°W 52.43' RICHARD W. SET 20d NAIL W/REMON TAG IN THE SOUTH SIDE OF A 3"- 5" MAPLE CLUSTER N41°E 28.39' STEADMAN SET 20d NAIL W/REMON TAG IN THE EAST SIDE OF A 12" MAPLE N39°W 47.66" LAND SET 20d NAIL W/REMON TAG IN THE N. SIDE OF 3" HICKORY N33°E 13.80" SURVEYOR SET 20d NAIL W/REMON TAG IN THE S. SIDE OF 6" WALNUT S77°E 5.84" NO. SET 20d NAIL W/REMON TAG IN THE S. SIDE OF 6" HICKORY S57°E 11.95" 11370 POSITION RECORDED BY BONNEMA (FOUND 1/2" IRON) N30°W 11.64' CORNER IS APPROXIMATELY 5.5' EAST OF C/L N-S GRAVEL ROAD (CURTIS ROAD) M-10 T2N R7W (BARRY COUNTY REMON MONUMENT) NORTH 10.04'

17,1996 of W. Stealman Date \_\_\_\_\_ Signed by . 11370 Surveyor's Michigan License No. .

P.A. 345 EATON COUNTY APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

PEER APPROVED 10 17 96 M