SURVEY & REMONUMENTATION

DEC 0 9 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

For corners in Benton Township Eaton County Located I	in: Corner Code #	
1. Public Land Survey T 3N	R <u>4W K-7</u>	99 DEC -2 PM 12: 57
T T T T T T T T T T T T T T T T T T T	R R	LINDA M. TWITCHELL REGISTER OF DEEDS EATON COUNTY, MICH.
In Section S T	R	LIBER 4 PAGE 100
3. Miscellaneous S T Property in Sec. S T	R	Register of Deeds Stamp & File Numb
4. Lot No, Recorded Plat 5. Private Claims		1 A B C D E F G H I J K L
1, Scott E. Koch, in a field survey on September 20, P.A. 74, Michigan P.A. of 1970, the corner points men with regulations and rules therefore as required in the States Department of the Interior, Bureau of Land M that the corner points mentioned in lines 3, 4 and 5 Michigan Board of Land Surveyors or by a Degree monumented, recovered, found as expressed below:	, 1999 do hereby state that under requirements of ntioned in lines 1 and 2 above were in conformance current manual of survey instructions of the United lanagement or by decree of a Court of Law and/or above were in conformance with the rules of the	2
NOTE: Not more than 2 corners, all in the same to on this certificate	own and range, may be recorded	8 -19 -20 -21 -22 -23 -2
A. Description of original monument and access	ssories and/or subsequent restoration:	10 30 -29 -28 -27 -26 -2
1827 – G.L.O. (Pg. 202, 264) Orange Risdon, s 10" Beech N56°W, 17 lks. 18" Sugar S56°E, 45 lks. No Date – County Road Commission Record		12 31 32 33 34 35 3
Box listed also) Witnesses: Maple NE Elm SE 3		
1972, September 6 - P.A. 74 LCRC (L. 2, Pg W. Steadman, PS 11370, "Du Gresham Highway and about clay pipeRaised location to	g. 651 - recorded February 2, 1980) Richard ug hole in the intersection of Hartel and to 2 ft. deep, found 3/4" iron pipe inside a 4" to surface with a 1/2" iron pipe." N61°E 59.28 ft. to N18°E 85.14 ft. Pole S45°E 43.95 ft.	
(Part "A" conti	nued on back)	
B. Description of corner evidence found and/o	or method applied in restoring or reestablishing	corner:
Found ¾" Pipe with cap #11370 in Monument E ¾" Pipe as a perpetuation of the original corner	Box, 0.5' East of centerline of Hwy M-100, and o	on centerline of Gresham. Accepted
C. Description of monument for corner and ac	cessories established to perpetuate locating th	e position of the corner.
Placed ½" Iron inside of ¾" Pipe with 2 ½" Alun S45°W, 53.13' to Nail & Tag #25828 S45°W, 53.10' to Nail & Tag #13038 S45°E, 44.60' to Nail & Tag #25828	8 in Utility Pole 9 in Utility Pole 3 in Utility Pole	1103. SCOTT E. KOCH
N25°E, 85.95' to Nail & Tag #13039 N30°W, 90.56' to Nail & Tag #13039		PROFESSIONAL SURVEYOR

Date September 21, 1999

Signed by

Surveyor's Michigan License No.

41103

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995

DEC (1 ≥ 1999

Corner K-7 Benton Twp.

SECTION SECTION A:

1973, January 15 - P.A. 132 Survey (L. 1, Pg. 283 - recorded Jan. 31, 1973) Kay Don Fluke, PS 18988, found 1/2" pipe with cap in Mon. box.

Witnesses:

NNE - 85.14 - Power Pole NE - 59.28 - Maple 20"

SE - 43.79 - Tel. Pole SW - 50.99 - Tel. & Power Pole

1974, January 28 - P.A. 74 LCRC (L. 2, Pg. 2 - recorded February 13, 1974) James E. Stephens, PS 16053, found a 1/2 inch iron pipe with tag #11370 and left in position.

Witnesses: Survey tag on the East side of a utility pole, S50°27'W 50.75 feet
Survey tag on the East side of a utility pole, N19°48'W 90.96 feet
Richard Steadman tag on the West side of a utility pole, N16°02'E 85.20

feet

- 1979, October 4 P.A. 132 Survey (L. 3, Pg. 100 recorded February 2, 1980) Richard W. Steadman, PS 11370, found 3/4" pipe in Mon. box and cites the witnesses from his LCRC in L. 2, Pg. 651.
- 1980, April 14 Unrecorded Survey Richard W. Steadman, PS 11370, corner is shown on survey but does not give reference to monumentation or witnesses.
- 1985, June 11 P.A. 132 Survey (L. 3, Pg. 907 recorded Nov. 1, 1985) Kay Don Fluke, PS 18988, does not give reference to monumentation. Shows overall measurement of 2640.68 feet to K-6.

Witnesses:

\$50W - 50.75 - Util. Pole \$N20W - 90.96 - Util. Pole \$N16E - 85.20 - Util. Pole

- 1985, September 30 P.A. 132 Survey (L. 3, Pg. 897 & 989 latter recorded Feb. 28, 1986) Robert G. Reed, PS 19004, found 1/2" iron with cap and cites the witnesses from Steadman LCRC in L. 2, Pg. 651.
- 1986, April 24 P.A. 132 Survey (L. 4, Pg. 16) Kay Don Fluke, PS 18988, references corner on survey as "1/2" pipe in Mon Box Recorded Act 74 ", but gives no other reference to witnesses.
- 1989, June 9 P.A. 132 Survey (L. 4, Pg. 776) Larry A. Bryan, PS 25832, found pipe & cap in monument box centerline of Hartel and Gresham Rds. and notes recordation in L. 2, Pg. 651. Shows overall measurements of 2611.04 feet to J-7 and 2637.42 feet to K-8. Witnesses: Found nail & tag #16063 East side power pole, S50°W, 50.86'

 Found nail & tag #11370 Southwest side power pole, S45°E, 43.93'

 Found nail & tag West side power pole, N15°E, 85.42'

 Found nail & tag South side 36" Maple, N60°E, 59.23'
- 1991, October 10 Unrecorded Survey Larry A. Bryan, PS 25832, cites same monument and witnesses as his survey in L. 4, Pg. 776. Shows overall measurement of 2640.54 feet to K-6.
- 1993, October 18 P.A. 132 Survey (L. 5, Pg. 680 recorded Oct. 18, 1993) Kay Don Fluke, PS 18988, references corner on survey as "Found 1/2" pipe in Mon Box in Hartel Rd. Recorded in Act 74 records, Eaton County", but gives no other reference to witnesses.
- 1995, November 12 P.A. 132 Survey (L. 6, Pg. 114 recorded Dec. 8, 1995) Larry L. Christensen, PS 30890, references corner as 1/2" pipe in mon box Rec. Liber 2, pg. 651 but gives no other reference to witnesses (corner is not shown on drawing).
- 1996, March 5 P.A. 132 Survey (L. 6, Pg. 276-277 recorded July 11, 1996) Fred N. White, PS 12034, found 3/4" pipe in monument box. Shows overall measurement of 2640.64 feet to K-6.

Witnesses: Found Nail & Tag #13039 SE side Utility Pole – S55°W – 53.15'
Found Nail & Tag #13039 East side Utility Pole – N16°W – 90.62'
Found Nail & Tag #13039 East side Guy Pole – N20°E – 85.50'
Found Nail & Tag #13039 SW side Utility Pole – S35°E – 43.91'