For corners in

18" Maple SW6

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FILED

95 NOV 28 PM 2: 03

EATON COUNTY	Located in: CHESTER TOWNSHIP Corner Code #	LINDA M. TWITCHELL REGISTER OF DEEDS EATON COUNTY, MICH.
Public Land Survey     Property Controlling in Section	T3N_R_5W C-8 TR	LIBER 3 FRE 612
3. Miscellaneous Property in Sec.	S TR	Register of Deeds Stamp & File Number
I, Maurice H. Mahieu, in a fiek 74, Michigan P.A. of 1970, the regulations and rules therefore Department of the Interior, Bur corner points mentioned in lines Land Surveyors or by a Decree recovered, found as expressed by		Islates  1 States  1 that the 6
on this certificate.	omers, all in the same town and range, may be recorded	9 10302926272525 11
	onument and accessories and/or subsequent restoration: one by Orange Risdon, U.S. Deputy Surveyor on March	

- 6" Beech NE 14
- 3. On November 15, 1875 Oscar G. Church County Surveyor recorded corner as "Stake FOBT &S" (book 1 pages 246-247 of County Surveyor Records.

(CONTINUED ON BACK)

B. Description of corner evidence found and/or method applied in restoring or reestablishing comer:
Found 5/8" x 24" iron rod 8" below gravel road surface. Iron falls 3' +/- East of centerline Ainger Road and on east-west fence line. Found nail in SE side utility pole, N48°E, 61.88 feet and also found nail in west side twin walnut S15°E 82.37 feet. Excavated 4' x 6' hole to a depth of 2.5 feet. Found no other evidence. Replaced 5/8" rod with standard 3/4" x 24" smooth iron rod with cap stamper "PA 345 PS #28414". This surveyor accepted the location of the 5/8" rod as the best position of the corner based on previous history of the rod.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" x 24" Iron Rod with Cap "P.A. 345 #28414" witnessed by:

2. Eaton County Road Commission grid map witnesses as:

Nail & Tag #28414 in North Side 15" Hickory, S 86 deg. W, 24.01'

Nail & Tag #28414 in South Side Utility Pole, N 48 deg. E, 61.49'
Nail & Tag #24814 in East Side 18" Walnut, S 29 deg. W, 46.50'
Nail & Tag #28414 Twin Walnut S 15 deg. E, 82.42'

Surveyor's Michigan License No. 28414

P.A. 345 EATON COUNTY PEER APPROVED 11/7/95

FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAIL 28, 1 REVISED MAY 14,1

MAURICE H. **MAHIEU** SURVEYOR NO.

## PART A CONTINUED

- 4. On March 1, 1877 O.G. Church County Surveyor recorded corner as "Stake FOBT&S" (Book 2, 42-43 of County Surveyor Records).
- 5. Laverne J. Hendryx RS #3276 in an Act 132 survey recorded in Liber 1, page 19, No description of corner, or witnesses are stated. Survey was dated April 24, 1971.
- 6. Sydney G. Bokovoy RS #19828 in an Act 132 survey recorded in Liber 1, pages 702-704 called for an iron bar witnessed by: 12" Walnut SW 46.83"

11" Birch SW 50.80'

1/2" iron West 33.00"

1/2" iron East 33.00"

Survey was dated July 28, 1973.

Power Pole N 52E 61.93'

- 7. Laverne J. Hendryx RS #3276 in an Act 132 survey recorded in Liber 1, Pages 502, no description of corner or witnesses are stated. Survey was dated October 25, 1973.
- 8. George D. Smith, RS #39098 in an Act 132 survey recorded in Liber 5, page 838, called for witnesses of: 1/2" iron West 33.00'
  1/2" iron East 33.00' 16" Twin Walnut S11E,82.47"

