

APR 2 7 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

94 DEC -1 AM 9: 40

Fo	r corners in	CHESTE	R TOWNSHIP	A. 1970		
EATON (County)		Located In:	Corner Code =##	REC	LINDA M. TWITCHELL REGISTER OF DEEDS EATON COUNTY, MICH.	
1.	Public Land Survèy	T3N R 5W T R T R T R	E=1			548
2.	Property Controlling	S R		MBER 3	Pq	OFU
	in Section	S R			•	•
3.	Miscellaneous	S R	-:	Register of Deeds S	amp & Fil	e Number
	Property in Sec.	S T R				
4.	Lot No	Recorded Plat		A B C D E	F G H	1 J K L
5.	Private Claims			<u> </u>	TIT	
				2 - 6 - 5 - 5	- i - j - i	
				3		
Maurice H. Mahieu , in a field survey on October 27 19 94				4 }	- 9 10	
4, 3	Waurice II. Waincu	5 	- - - 			
do	hereby certify that under re- lines 1 and 2 above were	oned 6 18 17 17	-1615			
cu	rrent manual of survey inst	Land '				
Ma	inagement or by a decree o	and 5 8 19 20	-2122	23 <u></u>		
ab	ove were in conformance w	e of a	$\dashv \dashv \dashv$			
	ourl of Law; established, pressed below:	re-established, monumented, re	AMONGMENTED, TECOVERCE, TOSIA	10 30 29	<u>_28</u> 27	26
	•	corners, all in the same town	and range, may be recorded	11 1 1	\rightarrow	_ _ _
146	on this certificate			12 31 32	_3334	
	\$11 tills \$2.1110001			13		

Description of original monument and accessories and/or subsequent restoration:
Original GLO survey by Orange Risdon in March 1827 indicates a post set at a distance of 73.10 chains.

GLO falling is 2.04 links East of E-13, Roxand Township.

Witnessed by: 10" Beech S25E 11 links

9" Beech S70W 38 links

Marginal notes in GLO notes, assumed to be County Surveyor, shows post was replaced with a long stone. 2. Witnessed by: 15" Elm S 50 1/2 deg. E 38.50'

(Over)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;

Found T. bar 2" below gravel road surface in centerline of Needmore Highway and fence line running South. Excavated 5' x 5' hole at an average depth of 3.5 feet. Found two small pieces of clay tile and two pieces of brick in general location of "T" bar. No other evidence found and set 3/4" x 24" iron bar with cap #28414 PA 345 in location of "T" bar. Performed traverse and determined distance East 2,645.26 feet to F-1 and South 2,191.54 feet to E-2. This surveyor accepts the position of the "T" bar as the best location of the perpetuation of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3/4" x 24" iron rod with cap #28414 PA 345, witnessed by:

Set Nail and Tag #28414 East side Utility Pole, South 93.60 feet

Set Nail and Tag #28414 North side Wood Fence Post, S 38 deg. W 40.40 feet

Set Nail and Tag #28414 North side 10" Apple, S 56 deg. W 74.35 feet MAHIEU Set Nail and Tag #28414 North side 18" Cedar, S 81 deg. W 127.70 feet NO. OFESSIO! 28414 APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28 Surveyor's Michigan License No.

> P.A. 345 EATON COUNTY PEER APPROVED 11/23/9

REVISED MAY 14 REVISED JAN

LIBERS Pg 519

Corner recorded in LCRC by James Stephens P.S. #16053 dated January 7, 1974 (L-2, P-69). A "T" iron was set in the South line of Section 32, Roxand Township, and on a projection of fence South of corner. Witnessed by:

Survey Tag West side Utility Pole, S 00 deg. 27' W 94.16'
Survey Tag North side Utility Pole, S 75 deg. 10' W 300.91'
Survey Tag South side 48" Maple, N 64 deg. 09' W 130.72'

- 4. Corner referred to in survey done by Bryan Land Surveys (L-5, P-228). Found "T" bar 2' North of centerline of road as in Liber 2, Page 69. Witnessed by: Found Stephens tag, West side Power Pole, South 94.27' Found Stephens tag, South side 48" Maple, N 65 deg. W 130.68' Set Nail and Tag North side 6" Cedar, S 80 deg. W 128.55'
- 5. Corner referred to in a survey done by Fred White PS #12032 in October 1982 (L-3, P-499) with no monumentation and witnesses noted.