

DEC 0 9 1999

FILED

Сору 99 DEC - 1 АН 10: 32

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Delta Township	riiiig Kequirei	ment of Act 74, wich. F.A.		TWITCHEST		
·			REGISTE	LINDA M. TWITCHELL REGISTER OF DEEDS EATON COUNTY, MICH.		
Eaton (County)	Located in:	Corner Code #	EATURO	ยยส ค.ศ. เคพายค.		
1. Public Land Survey	T <u>4N</u> R <u>3W</u> TR TR	C-8			a.	
2. Property Controlling S in Section S	T R T R B		LIBER	4 PAGE	96	
3. Miscellaneous S			Register of De	eds Stamp & File	Number	
Property in Sec. S T						
į						
4. Lot No, Recorde 5. Private Claims	d Plat		A B C D E	F G H I J	r K L M	
I, Anthony Bumstead state that under requirements of P.A. 7 and 2 above were in conformance manual of survey instructions of the Management or by a decree of a Courand 5 above were in conformance w Decree of a Court of Law; established below:	74, Michigan P.A. of 1970, ti with regulations and rules ti e United States Department It of Law and /or that the co ith the rules of the Michigan	herefore as required in the currer t of the Interior, Bureau of Lar rner points mentioned in lines 3, a Board of Land Surveyors or by	at 4 7 -8 at 4 5 4 5 4 -17		1	
NOTE: Not more than 2 corners, all	in the same town and range	e, may be recorded	9			
on this certificate.			10 - 30 - 29 - 11 - 32 - 31 - 32 - 13	28	25——25——35——36———36———36————36——————————	
A. Description of original monun	nent and accessories and	or subsequent restoration:				
2. Marginal note in the notes by H.A.William E S47°30'W 69 1/2'.	4 Sec. post" with e Eaton County Roa ms in 1923 show wi 70, survey recorde n pipe, replaced w m N34°E 59.75', 7"	witnesses: Beech 6 N d Commission copy of thesses with no monuted in Liber 1 of Surveith 1/2" iron pipe & Elm N42°W 62.94'. back) in restoring or reestablishing corrections of Nixon Road. to +3 feet and found	62°E 11, Do 8 N6 the Original Go ment noted: B As eys, Page 968, G Mon. box" with mer: Witnesses matches nothing further	5°W 20. Evernment Surent N48°57'E (lated 7-2-75 witnesses: ed with those. Accepted	rvey 68 1/2', calls p.Pole e in 1/2"	
C. Description of monument Set standard Remonument Found nail & tag North Found nail & tag #11370 Found nail & tag #12034 Found nail & tag in Nor Found nail in South sid	side power pole, som pole,	S85°E, 34.66' pole,S85°E, 34.67' 2" dead Elm, N35°E, 5 e, West, 29.30'	P.S. 41095" as 1	ANTHONY BUMSTEA PROFESSION SUBVEYOR	Y X	
Signed by Author Lines No.	Zember 1	Date//- 3	0-99	41095	S JE LAND	
Surveyor's Michigan License No.	41095			*********	44	

A:) continued

- 4. Steadman recorded survey in Liber 1 of Surveys, Page 973, dated Oct. 7, 1975 calls for same monument & witnesses as #3 above.
- 5. Steadman recorded survey in Liber 2 of Surveys, Page 82, dated July 6, 1976 calls for same monument &
- 6. Fouty P.S. #18989, recorded survey in Liber 3 of Surveys, Page 137, dated Apr. 14, 1980 calls for same monument & witnesses as #3 above.
- 7. Fourty recorded survey in Liber 3 of Surveys, Page 138, dated Apr. 14, 1980 calls for same monument & witnesses as #3 above.
- 8. Fouty recorded survey in Liber 3 of Surveys, Page 140, dated Apr. 14, 1980 calls for same monument & witnesses as #3 above.
- 9. Steadman recorded survey in Liber 3 of Surveys, Page 245, dated Dec. 28, 1980 calls for same monument & witnesses as #3 above.
- 10. L.C.R.C. recorded by Richard W. Steadman in Liber 2 of Corners, Page 741, dated Oct. 15, 1981 calls for same monument & witnesses as #3 above with one additional witness: Power Pole West 29.26'.
- 11. Steadman recorded survey in Liber 3 of Surveys, Page 518, dated March 28, 1988 calls for same monument & witnesses as #3 above.
- 12. Fluke recorded survey in Liber 5 of Surveys, Page 896, dated Oct. 25, 1994 shows corner & calls for Act 74, L2 - Pg. 741.

SURVEY & REMONUMENTATION

DEC 0 9 1999

SECTION