MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 34 NR 4 W

DESCRIPTION OF CORNER Closing corner common to Sections 2 and 3 on north boundary of T33N,R4W

DESCRIPTION OF CORNER MONUMENT Left 1" pipe in place

WITNESSES TO CORNER

16" Eim - 811W - 37.3 feet

10" Eim - 873E - 66.2 feet

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial retracement of this township. Found 1" pipe in place previously established by Marcus Schaaf, Registered Land Surveyor, from the government BTs. A 30" Elm, recently out and lying at road-side was identified as the SW government BT about 30 years ago. Corner falls about 10' east of a fence line south.

Corner to Sections 34 and 35, T34N,R4W is 30 links east.

Corner was witnessed August 11, 1959.

SURVEYORS SEAL

SIGNED_ LAND SURVEYOR DATES/28/59_