MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T 34 NR 4 W

			Chebo	Aga <u>u-E</u> m	metCOUNTY	1
DESCRIPTION OF CORNEL	R 1/4 corne	er com	mon_to_s	ections	19 and 24	
DESCRIPTION OF CORNER	MONUMENT	LFH-:	pipe_wit	1_4"_br	ass_cap	
WITNESSES TO CORNER						
	7# Elm	-	847E		64 links	
	8" Elm	-	ифом	-	63 links	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial resurvey of T34NR4W. Found 1" pipe with concrete base in place at corner, previously established by Marcus Schaaf, Reg. land surveyor, about 1927. No remaining government evidence, probably remover during fireline construction. Corner checks good for midpoint, but is slightly out of line between section corners.

Corner was placed and witnessed September 9, 1959.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 9/11/59