MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 34 NR 4 W

		Emme	t	COUNTY
Section cor	ner co	mmon to	Section	18 13-14-23-24
MONUMENT_	Tu x 3	24 pipe,	_peroπ	surface_of_road
TO, ETM	<u>-</u>	BOTE	_	46 links
7" Maple	_	83 W		831 links
14" Elm	-	N2TA	-	54½ Links
	MONUMENT	MONUMENT	Section corner common to MONUMENT 1" x 24" pipe, 10" Eim - 861E 7" Maple - 83W	Section corner common to Section MONUMENT 1" x 24" pipe, below 10" Elm - 861E - 7" Maple - 83W -

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established by Forestry Division survey crew while making a partial retracement of this township. Could find no evidence of a previous corner in a thorough search of the road intersection. Set corner on line over 1/4 corner and section corner west, making the half miles of equal length. This places the corner very near to the centerline of the road north, and would place the 1/4 corner to Sections 13 and 24 in the centerline of the road south. Proportionate measurement was not considered since it would place the corner too far east to conform with the roads or the 1/4 corner south, which is considered a good corner. Falls about 5' north of the apparent centerline of the present L-W county road at this point.

Corner was placed and witnessed August 25 1959.

SURVEYORS SEAL

SIGNED LEMENT SURVEYOR DATE 8/27/59