## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 34 NR 4 W

					Emmet		COUNTY	ſ
DESCRIPTION	Of	CORNER	Section co	rner co	mmon to	Section	ns 14-15-22-23	
DESCRIPTION	OF	CORNER	MONUMENT_	Left 1	rşi azel	e_iron	in place	
WITNESSES '	то	CORNER .						
			8# Elm	. <b></b>	3157W 		28.0 feet	
			8" Elm	-	N38E		III.9 feet	
							<b></b>	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew while making a partial retracement of this township. Found 12 angle iron in place in center of roads N-S-E-W, which appears to have been accepted as the corner by adjoining occupation. Government corner tree probably removed in construction. Considered as best available evidence of the proper position for this corner, and was accepted in this survey.

Corner was witnessed August 11, 1959.

SURVEYORS SEAL

SIGNED MULLEL J. DELLES DATE 8/27/59