REMONUMENTATION

MAY 0 5 1997

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN EMMET COUNTY
RECORDED

96 DEC 31 PM 2: 25

BEGISTER OF DETRE

LIBER A

Register of Deeds Stamp & File Number

6

10

11

COlaum	Water Trans. In case of the ca	
EMMET	Located in:	Corner Code #
(County)	I	TOWNSHIP
1. Public Land Survey	T <u>34</u> R 6 W T 34 R 5 W	M-5 A-5
ECRP#127	TR TR	
Property Controlling in Section	S T R S T R	
 Miscellaneous Property in Sec. 	S T R S T R	

I, Richard E. Celke , in a field survey on 20 December , 19 96 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more that 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-5..... corner common to Sections 7, 12, 13, & 18, T34N, R6W
A-5..... corner common to Sections 7, 12, 13, & 18, T34N, R5W

See Outline of Corner History on back.

Corner was extensively used at the turn of the century. It must have been destroyed during the rebuilding of Cemetery Road.

Present corner was set by Consumers Power surveyor, in 1961. I believe he extending N1/2 mile of sec. southerly opposite fence to the west.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-5.... corner common to Sections 7, 12, 13, & 18, T34N, R6W

A-5..... corner common to Sections 7, 12, 13, & 18, T34N, R5W 🗸

P.A. 345 OF 1990
Emmet County
P.E. OSUKE

RICHARD E

OELKE PROFESSIONAL

SURVEYOR

No.

33983

0113510

Found 3/4" iron rod, 1.2' long, in centerline of Cemetery Rd. above T-iron set by Consumers in 1961.

WITNESSED AS FOLLOWS:

N26°E 86.31' p.p., nail capped PS# 15401 in E face

S88°E 35.08' T-iron, capped with Consumers Power tag

p.p., nail capped PS# 15401 in E face N26°E 86.31' S88°E 35.08' T-iron, capped with Consumers Power tag S53°E 25.95' p.p., nail capped PS# 27463 in SW face p.p., nail and MDOT flasher in SW face 25.95 S53°E p.p., nail and MDOT flasher in N face S53°E 26.041 S37°W 12" birch, blaze on side of tree 66.121

S48°W 74.11' NE cor. of hse.

S77°W 31.51' 12" red pine, nail capped PS# 27463 & 33983 in N face

N74°W 31.82' 6" red pine, nail capped PS# 30095 in N face

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5.... corner common to Sections 7, 12, 13, & 18, T34N, R6W

A-5..... corner common to Sections 7, 12, 13, & 18, T34N, R5W

Replaced 3/4" iron rod with a 2" diameter, 30" long PVC pipe, with a base magnet and a standarad Emmet County Survey Remonumentation Program cap. This position is accepted as a careful and faithful perpetuation of the original corner.

NO NEW WITNESSES TAKEN

igned by R.E. CLUE	Date	20 December 1996	
ervevor's Michigan License No. 33983			

PAGE ______

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 127

34-6-M5 = 34-5-A5 T34N R6W 7/12/13/18 CEMETERY ROAD

Date	Surveyor	Found Witnesses Notes
1840	GLO	Set post S31E 25L 14" beech N22W 43L 10" beech
1881	Keep	ran S/L Sec. 7, appears to have fd. cor.
1885	Keep	ran S/L Sec. 7, appears to have fd. cor.
1894	Main	fd. stone, 1) N37E 59L 4" maple 2) S86E 28.5L 4" maple
1903	Palmer	fd stone with "x" on top.
1961	Bold	set "T-iron", survey for consumers power. 3) NNE 99.55' 8" maple 4) E 33.00' "T-iron" 5) SW 29.15' nail/washer twin elm
1963 1965	G. Young G. Young	Fd "T-iron", survey for Spears (487). Fd "T-iron", survey for Seiler (567).
1970	MDOT	Fd 3/4" iron bar set mon. box. 6) S85E 36.67' fence post 7) S50E 26.00' pp 8) S50W 74.18' ne cor. hse fnd.
1977	Green	Fd 3/4" iron rod, survey for Kauffman. 9) NE 86.46' pp 4) E 32.85' "T-iron"
1977	G. Young	Fd 3/4" iron in mon. box, surveys for (Ruzinsky(1280), and Eppler(1286). 7) S53E 26.00' pp 10) S78W 31.75' 4" pine
1983	J. Young	Fd. 3/4" iron bar, survey for Gokee. as witnessed by MDOT.
1985	Green	Fd 1" iron rod, survey for Rasmussen. 7) S46E 25.98' pp 11) S37W 66.75' 8" birch 10) S83W 31.90' 6" pine
1986	Trowbridge	LCRC (L2-161), fd 3/4" iron bar in mon. box. 9) N31E 86.40' pp 7) S47E 25.98' pp
	All Control	10) S82W 31.56' 8" pine
1994	Oelke	Fd 3/4" iron rod, survey for R.G. Properties.
1995	Chaimberlain	Fd 3/4" iron rod, survey for Germond. as witnessed in (L2-161)
1995	Swenor	Fd 1" rod, surveys for Brecheisen(L561-827). as witnessed in (12-161)