MAY 0 5 1997

COMMISSION

Located in:

T.34/NR6W T_R_

For corners in

1. Public Land Survey

E.C.R.P#121

on this certificate.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Corner Code ##

EMMET COUNTY RECORDED

96	OEC	31	F	М	2.	21
			•	11	/:	71

Allam a Sign

2. Property Controlling	T R S T R	
in Section	S _ T _ R	-
3. Miscellaneous	S T R	Register of Deeds Stamp & File Number
Property in Sec.	S T R	***
4. Lot No, F	Recorded Plat	
5. Private Claims		
		3 5 4 4 3 3 2 1 1
1, Thomis O. Dwenor	, in a tield survey on November 27.1	19 76 . 5
· •	uirements of P.A. 74, Michigan P.A. of 1970, the corner point of conformance with regulations and rules therefore as re-	
current manual of survey instri		
	a Court of Law and/or that the corner points mentioned in lir th the rules of the Michigan Board of Land Surveyors or by	
	re-established, monumented, re-monumented, recovere	
expressed below;		10 -30 -29 -28 -27 -26 -25
NOTE: Not more than 4 c	orners, all in the same town and range, may be rec	corded 11

- A. Description of original monument and accessories and/or subsequent restoration:
 - Section Corner common to Section 10, Section 11, Section 14, and Section 15, T34N R6W

(SEE BACK OF PAGE FOR HISTORY)

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Visited location of stone with cross. Found that the stones location did not correlate with the 1981 witnesses by James H. Green. Further the stones position, was approximately 7.5' west of a north and south fence line. Began excavation where the three 1981 witnesses intersected. There was an obvious deprection at the witness intersection. At approximately 1 foot depth began to find large chunks of charcoal as referred to by J. Keep in 1885. Charcoal was found to approximately 18". Placed a 2" diameter, 30" long PVC Pipe with a Base magnet and a standard Brass Emmet County Remonumentation Cap per witnesses referred to below.

APPROVED LAND CORNER P.A. 345 OF 1990 **Emmet County** R. E. OELLE 12-30-96

THIS CORNER IS ACCEPTED BY THE EMMET COUNTY REMONUMENTATION GROUP AS A FAITHFUL AND CAREFUL PERPETUATION OF THE ORIGINAL CORNER.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Placed a 2" diameter, 30" long PVC Pipe with a Base magnet and a standard Brass Emmet County Remonumentation Cap at the intersection of witness no. 4) and no. 5) referred to below. Corner falls in center of Charcoal deposit. Reason for 1900 era surveyors placing charcoal becomes apparent, when landowners find reason to move the stone, in this case 10.5"+/- west of where Keep placed corner.
 - THOMPS D. * : SWEHOR LAND SHAVEYOR AND SAND

(3) N40°E 29.20' - (2)-11" Maple (Found spike with 15401 cap). Green measured 29.08' (4) S32°W 8.08' - 22" Maple (Found spike with 15401 cap)**

- (5) N44°W 28.87' 7" Maple (Found spike with 15401 cap)**
- (8) N88°E 27.88' 8" Maple (Set spike with 37282 cap)
- (9) 2.5' west and 0.0' north to T-fence intersection. Fenceline runs north/south, and west at intersection. Witnesses donoted as " ** ".used due to height of spike in tree @ (3).

13 THE PART CONTOCON TO SECOND CONTRACTOR OF THE PART		, , , , , ,
Signed by Thomas D. Sueroz	Date _	/57
20200		
Surveyor's Michigan License No		FO

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 1975

REVISED JAN., 1983

PAGE 138

EMMET COUNTY REMONUMENTATION PROGRAM CORNER NO. 121 T34N R6W - I-5

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

Date	Surveyor	Found	(Witnesses)	
1840	GLO	Set Post Corner	(1)	Beech 16 - N80E 45
			(2)	Sugar 18 N18W 23
1885	J.Keep	Est 1/4 Post w/charcoa & Large Stone w/cross	•	
1981	J.H.Green	Found Stone with cros	(4)	N40°E 29.08' - (2)11" Maple S32°W 8.08' - 22" Maple
			(5)	N44°W 28.87' - 7" Maple (L.2, P.78, LCRC)
1986	J.H.Green	Section Subdivision us stone as S.E. Cor. Sec.	~ .	no witnesses
1992	R.E.Oelke	Found Stone with cros	5	no witnesses