SURVEY & REMONUMENTATION

MAR 04 1998

STATE OF MICHIGAN EMMET COUNTY RECORDED

LAND CORNER RECORDATION CERTIFICATE

97 DEC 30 PM 1: 15

For corners in SECTION	riling Kequire	ment of Act 74, Mich. P.A	. 1970			
EMMET	Located In:	Corner Code #	Ale	ard Size		
(County)				y		
			REGIS	TER OF DEEDS		
1. Public Land Survey	T <u>35N</u> R 4W	A11				
	T R					
ECRP # 156 A	T R		A TOTAL OF			
2 Branarty Controlling C	T R		LIBER A	PAGE 224		
2. Property Controlling S in Section S	T R		·			
3. Miscellaneous S	T R T R					
Property in Sec. S	T R		Register of Deeds Sta	egister of Deeds Stamp & File Number		
-	-		`	9		
4. Lot No, Recorde	d Plat			*		
5. Private Claims			A B C D	е г дні јк ц		
			2 6 5	4 · 3 · 2 1		
		•	3			
I. Michael A. Trowbridge in	a field survey on	December 26th , 19 97		9 · 10 · 11 · 12		
do hereby certify that under requirementioned in lines 1 and 2 above v	tents of P.A. 74, Michiga vere in conformance with	an P.A. of 1970, the comer portions and rules therefor	oints 5			
required in the current manual of surve	ey instructions of the Unite	ed States Department of the Inte	rior. 6 - 18 17 -	16 - 15 ¹ 14 · 13		
Bureau of Land Management or by a mentioned in lines 3, 4 and 5 above v	decree of a Court of Leaver in conformance with	aw and for that the corner po	oints 7			
Professional Surveyors or by a Decree	of a Court of Law; estab-	lished, re-established, monumer	sted, 8 - 19 20	21 22 23 24		
re-monumented, recovered, found as ex	kpressed below:		9 - · · ·			
NOTE: Not more that 4 comers, a	all in the same town an	d range may be recorded		28 - 27 - 26 - 25		
on this certificate.		a range, may be recorded	10	33 34 35 36		
			12 31 32-	33 34 35 36		
A. Description of original monum	ent and accessories and	d/or subsequent restoration:	13			
A11, CORNER COMMON TO	SECTIONS 25 & 36. T	35N REW AND COMMON	TO SECTIONS 20 8 21 :	FORM DAW		
			TO OLO HOMO DO & 31,	133N, N4W		
SEE CHRONOLOGY ON BAC	K OF THIS FORM FOR	CORNER HISTORY.				
				D LAND CORNER		
				345 OF 19 90 Imet County		
,				· DELKE		
			ECRE			
B. Description of corner evidence	found and/or method a	ipplied in restoring or reestal	olishing corner:			
A11, CORNER COMMON TO	SECTIONS 25 & 36, T	35N, R5W, AND COMMON	TO SECTIONS 30 & 31, 1	735N, R4W		
Found 1" pipe, 2' long, on top box. This noted iron material 8	of a 3/4" solid shaft, : & monument box is in a	2' long (total 4' in length) in paved east-west, & south r	side a standard Emmet Co oad intersection, in line w	ounty monument		
& barbed wire fence north.			• • • • •	P-2-		
	°W 63.15' Power Pole P E 45.32' Corner Fer	e [nail at southwest face (plance Post (to south face)	aced 27463 cap & spike	above existing nail)]		
(7) N 5°	' E 45.32' Corner Fe	nce Post (to south face)				
C. Description of monument for c	orner and accessories ϵ	stablished to perpetuate loc	ating the position of the c	corner:		
A11, CORNER COMMON TO S						
The pipe & material noted above magnet and a standard brass E This position is accepted as the	mmet County Survey R	emonumentation Program ca	p, & a standard Emmet C	PVC pipe with a base county monument box.		

8" Scotch Pine, 27463 cap & nail in east face S50° W 71.01 12-29-97 27463 Surveyor's Michigan License No. FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Corner Fence Post, 27463 cap & nail in west face

12" Aspen, 27463 cap & nail in west face

ADDITIONAL NEW WITNESSES:

9) N5° E

10) S34° E

45.57

75.03

MICHAEL A. ROWBRIDGE

EMMET COUNTY REMONUMENTATION PROGRAM CHRONOLOGY OF GLO CORNER

REMON. CORNER #156

TANK A 12 many afternoon

LCRC #35-04-A11 TOWNSHIP...SPRINGVALE

LIBER A

PAGE 22

CORNER COMMON TO SECTIONS 25 & 36, T35N, R5W, and 30 & 31, T35N, R4W

DATE	SURVEYOR	FOUND/SET	WITNESSES		
1840	GLO	Set Post	1) N62°W 2) S58°W	48 lks. 16 lks.	14" Beech 18" Hemlock
1951	T.F.Schweigert	Iron Rod	No witnesses noted		
1958	ECRC 400-401-1	Found 3/4" rein. rod.	3) North4) Southwest5) Southeast	44.25' 109.4' 57.8'	Fence Post Power Service P 6" Birch
1970	Schweigert & Young Survey Map	Found 1/2" Iron Pipe	No witnesses noted		
1972	R.E.Bidstrup Survey Map L.248, Pg.967	Found 1/2" Iron Pipe	6) N56°W 7) N2°W 8) S30°E	63.11' 44.47' 51.95'	Power Pole Fence Cor. Post 14" Aspen
1975	J.H.Green Survey Map L.259, Pg.26	Found 1" Pipe	6) N53°W 8) S30°E	63.12' 52.00'	Power Pole 14" Poplar
1980	J.H.Green LCRC : L.2, Pg.48	Found 1" Pipe in Monu. Box	6) N53°W 8) S30°E	63.12' 52.00'	Power Pole 14" Poplar
1982	J.H.Green Survey Map	Found 1" Pipe in Monu. Box	6) N53°W 8) S30°E	63.12' 52.00'	Power Pole 14" Poplar
1988	J.H.Green Survey Map	Found I" Pipe in Monu. Box	6) N53°W 8) S30°E	63.12' 52.00'	Power Pole 14" Aspen
1989	J.H.Green Survey Map	Found 1" Pipe in Monu. Box	6) N53°W 8) S30°E	63.12' 52.00'	Power Pole 14" Aspen
1991	M.A.Trowbridge Survey Map	Found 1" Pipe in Monu. Box	6) N54°W 7) N5°E 8) S30°E	63.15' 45.32' 51.95'	Power Pole Cor Fence Post 14" Aspen
1992	T.D.Swenor Survey Map L.471, Pg.365	Found 3/4" Pipe	6) N53°W 8) S30°E	63.12' 52.00'	Power Pole 14" Popular
1992	T.D.Swenor Survey Map	Found Iron in ?	No witnesses noted		
1993	T.D.Swenor Survey Map L.496, Pg.158	Found 3/4" Pipe	6) N53°W 8) S30°E	63.12' 52.00'	Power Pole 14" Popular
1994	T.D.Swenor Survey Map	Found 1" Pipe in Monu. Box	6) N54°W 7) N5°E 8) S30°E	63.15' 45.32' 51.95'	Power Pole Cor Fence Post 14" Aspen
1995	T.D.Swenor Survey Map	Found 1" Pipe in Monu. Box	6) N54°W 7) N5°E 8) S30°E	63.15' 45.32' 51.95'	Power Pole Cor Fence Post 14" Aspen
1996	T.D.Swenor Survey Map	Found 3/4" Pipe	6) N53°W 8) S30°E	63.12' 52.00'	Power Pole 14" Popular