STATE OF MICHIGAN EMMET COUNTY RECORDED

1994 DEC 14 PH 3: 06

ECRP # 53 APR 27 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For corners in EMMET (County)		· ·····g rioquite	A. 1970	
		Located In:	Corner Code ##	Elenna A. Signi REGISTER OF DEEDS
1.	Public Land Survey	SECTION 04 T T36 N R - R04 W T _ R _ R	E3	LIBER A PAGE 46
2.	Property Controlling in Section	S T R S T R		8 79 0332
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4.	Lot No.	, Recorded Plat		*
		, 11000.000		ABCDEFGHIJKL
				2 6 5 4 3 2 4 3

11/18 , in a field survey on . in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

SEE BACK OF THIS FORM FOR CHRONOLOGY...

10

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" REROD, CAP NO. 27463, & WITNESSES AS REPRESENTED IN A CORNER RECORD BY TROWBRIDGE IN 1984, LIBER 2, PAGE 123, & ALSO AS NOTED ON THE BACK OF THIS FORM; I FOUND THIS POSITION TO BE BASED ON THE BEST AVAILABLE EVIDENCE FOR THIS CORNER, & IN CONFORMITY WITH THE ABOVE NOTED CORNER RECORD.

APPROVED LAND CORNER P.A. 345 OF 1990 **Emmet County** 21 Nov. 1994

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. TO TO LAND MANUAL TO A STATE OF THE PARTY OF SET A 2" DIAMETER, PVC PIPE WITH A BASE MAGNET & A STANDARD BRASS EMMET MICHAEL A TROUPOBBOR COUNTY REMONUNERTATION CAP IN THE SAME POSITION AS THE 1/2" REROD NOTED IN "B" ABOVE, & WITH THE SAME WITNESSES AS NOTED IN LIBER 2, PAGE 123, &

6" HAPLE N74"N 9.56" 7" MAPLE N1'E 5.09' 7" MAPLE S8'E 20.20'

AS FOLLOWS:

ESTABLISHED A 4TH WITNESS AS FOLLOWS:

12" MAPLE N67°E 15.48' with 27463 cap & nail

PLACED_27463 cap & nail spike in above (3) prior witnesses. above.

CHRONOLOGY OF GLO CORNER

REMON. CORNER # 53 LCRC # 36-04-E3

TORNSHIP...MAPLE RIVER

CORNER COMMON TO SECTIONS 4-5-8-9, T36N, R4N

SURVEYOR: MICHAEL A. TROWBRIDGE, PLS # 27463

E.C.R. CONTRACT # 94-2

DATE	SURVEYOR	FOUND	SET (WITKESSES)
1840	GLO	SET POST	BEECH 8 N24E 11 BEECH 16 S49W 23
1984	TROWBRIDGE, CORNER REC, L. 2, PG. 123	SET 1/2" REROD	6" MAPLE N74W 9.56 7" MAPLE N1E 5.09 7" MAPLE S8E 20.20

1984-1992 TROWBRIDGE SURVEYS OF RECORD SHOWING CORNER & CONFLICTS; CORNER & WITHESSES SAME AS L. 2, PG. 123.

> SUPPLEMENTAL INFORMATION ATTACHED WORKING DRAWING SHOWING AREA SURROUNDING CORNER WITH CONFLICTS, ETC., & OTHER PERTINENT INFORMATION.....

3604-E3, MAT